

CUSTOMER SERVICE BULLETIN

CSB Number

Date

LYNK Solar Gateway – DC-DC Power Supply

URGENCY

HIGH:

MEDIUM: Action immediately Action by next possible occasion

LOW:
Action if necessary

GENERAL:
General Information

855-0011 Rev A MAR 22 2022

PRODUCTS AFFECTED

LYNK Solar Communication Gateway (950-0015).

SYMPTOM OBSERVED

Later build of LYNK Solar Communication Gateway (950-0015) does not include a DC-DC Power Supply (950-0019). The following note from the LYNK Solar Manual is now incorrect as the 950-0019 DC-DC Power Supply is discontinued and not available.

▲ NOTE

An external 950-0019 DC/DC AEBus Power Supply IS REQUIRED for the AES batteries listed below. This part can be purchased separately for systems requiring them.

- 42-48-6650 with a serial number before DET424820275xxxx
- 44-24-2800 with a serial number before DET442420225xxxx

POSSIBLE CAUSE

Product discontinued.


FIELD CORRECTIVE ACTIONS

Replace the LYNK Solar (950-0015) with a LYNK II Communication Gateway (950-0025) for

- 42-48-6650 with a serial number before DET424820275xxxx
- 44-24-2800 with a serial number before DET442420225xxxx

The LYNK II can receive power from the battery terminals to the Phoenix connector terminal PINs 7 & 9:

PIN Assignments for Phoenix 12-PIN Connector							
2	4	6	8	10	12		
RELAY 3 COM	RELAY 3 N/O	RELAY 2 N/0	RELAY 2 COM	RELAY 1 N/O	RELAY 1 COM		
1	3	5	7	9	11		
CAN HIGH	CAN LOW	CAN GND	POWER GND	POWER Vin (13-90V)	RELAY 1 N/C		



- End of Document -

Page 1 of 1 Form: 880-0002 Rev C